



Tech Info Library

Apple IIe Hardware: Reference Manual Errata

Revised: 9/21/84
Security: Everyone

Apple IIe Hardware: Reference Manual Errata

=====

Page 133 in Chapter 6: Switching I/O Memory, Table 6-5

READS:

| | | | | | |
|-----------|------------------------|--------|-------|--------|-------|
| SLOTCXROM | Slot ROM at \$3x00 | \$C007 | 49159 | -16377 | Write |
| | Internal ROM at \$Cx00 | \$C006 | 49158 | -16378 | Write |

SHOULD READ:

| | | | | | |
|-----------|------------------------|--------|-------|--------|-------|
| SLOTCXROM | Slot ROM at \$3x00 | \$C006 | 49158 | -16378 | Write |
| | Internal ROM at \$Cx00 | \$C007 | 49159 | -16377 | Write |

Apple Technical Communications

Tech Info Library Article Number:164